







① PIPE END CAP ATTACHMENT



PRESS FIT END CAPS INTO THE ENDS OF THE CROSS PIPE AT BOTTOM OF LEG (2 PER LEG REQ.)


N.T.S.

② TYPICAL 2 X 10 END CAP ATTACHMENT



N.T.S.

③ TYPICAL 2 X 10 PLANK ATTACHMENT



N.T.S.